

12 Nettlehill Road Livingston WEST LOTHIAN EH54 5DL






Tel: +44 (0) 1506 444160 sales @hewit.com www.hewit.com


Universal Corner Gauge

Eliminate the guess Work!

All you need is the gauge and a spare piece of board the same thickness as your cover board.



Tools needed




Corner ready for cutting



Locate the corner gauge onto the corner of the board



Gauge Located




Place spare piece of board, the same thickness as the cover board, into position against the gauge.




Mark along board with pencil.




Pencil line showing trim line. Cut off along line with knife or Scissors



Or trim directly with scalpel or knife.



Corner trimmed.



Cloth turned in

A PERFECT CORNER EVERY TIME!